



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/18/18 at 2:30:22 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAY Ownership History The number of owners is estimated		A Owner 1
Year purchased		2005
Type of owner	- Jenney	Personal
Estimated length of ownership	CARFAN	13 yrs. 1 mo.
Owned in the following states/provinces	LOWNER	Ohio
Estimated miles driven per year	June .	_ /
Last reported odometer reading		63

CARFAX Title History  CARFAX quarantees the information in this section	A Owner 1
alvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	Guaranteed No Problem
Not Actual Mileage   Exceeds Mechanical Limits	Guaranteed No Problem

CARFAX Additional History	Owner 1
Not all accidents / issues are reported to CARFAX	
Total Loss  No total loss reported to CARFAX.	No Issues Reported
Structural Damage  No structural damage reported to CARFAX.	No Issues Reported
Airbag Deployment	No Issues Reported

Odometer Check.	No Issues
No indication of an odometer rollback.	Indicated
Accident / Damage	No Issues
No accidents or damage reported to CARFAX.	<b>☑</b> Reported
Manufacturer Recall	Recall
At least 1 manufacturer recall requires repair.	Reported

## CARFAY Detailed History Owner 1 Date: Mileage: Source: Comments: 07/25/2005 63 Ohio Title issued or updated Motor Vehicle Dept. First owner reported Coeur d Alene, ID Titled or registered as Title #1806659391 personal vehicle 08/03/2005 Vehicle Exporter Vehicle exported from Los Angeles, CA and imported to Japan 05/29/2015 FCA US LLC Manufacturer Safety recall issued NHTSA #15V-313 #R25 DRIVER AIRBAG INFLATOR Status: Remedy available Click here for a copy of the owner letter for this Recall or call 1-800-853-1403 if you have any questions or need additional information on this recall. Learn more about this recall Description: THE DRIVER AIRBAG INFLATOR HOUSING MAY RUPTURE, DUE TO EXCESSIVE INTERNAL PRESSURE, DURING NORMAL AIRBAG DEPLOYMENT EVENTS. THIS CONDITION IS MORE LIKELY TO OCCUR IF THE VEHICLE HAS BEEN EXPOSED TO HIGH LEVELS OF ABSOLUTE HUMIDITY FOR EXTENDED PERIODS OF AN INFLATOR RUPTURE, DURING AIRBAG DEPLOYMENT EVENTS, COULD RESULT IN METAL FRAGMENTS STRIKING AND POTENTIALLY SERIOUSLY INJURING THE VEHICLE OCCUPANT(S). Remedy: THE DRIVER AIRBAG INFLATOR MUST BE REPLACED. FCA US LLC Manufacturer Safety recall issued 07/01/2016 NHTSA #16V-352 #S43 PASSENGER AIRBAG INFLATOR Status: Remedy Not Yet Available Click here for a copy of the owner letter for this Recall or call 1- 800-853-1403 if you have any questions or need additional information on this recall Learn more about this recall Description: THE FRONT PASSENGER AIRBAG INFLATOR MAY RUPTURE, DUE TO EXCESSIVE INTERNAL PRESSURE, DURING NORMAL AIRBAG DEPLOYMENT EVENTS. THIS CONDITION IS MORE LIKELY TO OCCUR IF YOUR VEHICLE HAS BEEN EXPOSED TO HIGH LEVELS OF ABSOLUTE HUMIDITY FOR EXTENDED PERIODS OF AN INFLATOR RUPTURE, DURING AIRBAG DEPLOYMENT EVENTS, COULD RESULT IN METAL FRAGMENT(S) STRIKING THE VEHICLE OCCUPANT(S) RESULTING IN SERIOUS INJURY OR DEATH. Remedy: THE PASSENGER AIRBAG INFLATOR MUST BE REPLACED.